

Windows containing PCB

Item no. 17 21 120 3

EAL: 17 06 02

NS: 7211

Windows containing PCB



Is to contain

- ✓ Double glazing units manufactured in Norway between 1965 and 1975.
- ✓ Imported double glazing units produced until 1980.
- ✓ Double glazing units without tamp/imprint of year produced.

Is not to contain

- ✓ Double glazing units newer than described above
- ✓ Other types of waste

Description

Sealing glue containing PCB's may have been used in double glazing units produced in the time period specified above. This is classified as hazardous waste and must be amassed separately. The production year is imprinted in the space between the panes. Units that can not be identified are to be delivered as a double glazing units containing PCB's.

Collection

Standing on an L-stand or well-guyed on a EUR-pallet. The panes must not be taken out of the wooden window frame.

Processing

Double glazing units containing PCB's are processed in approved treatment facilities with special authorization. The panes are visually checked before the glass is cut out. All waste containing PCB's is sent for destruction.

Recycling

The units are cut up and the material sent to recycling. The wooden frames with spacer rails and sealant containing PCB's are recycled for energy/destroyed at an approved waste-to-energy plant.

Non-compliance

Broken double glazing units are processed as an individual fraction. The driver will not take hazardous waste if the declaration is not completed.

Reference to regulations [Waste Regulation](#) [Ruteretur.no](#)